



O-RING REINSTATED IN HIGH PRESSURE CONTROL VALVE TOPWORKS


This product notice is to inform you that, based on feedback from customers, we are reinstating the extra O-ring on the atmospheric side of our High Pressure Control Valve Topworks.

This reverses the change announced in our [June 18, 2026 notice](#). Removing the O-ring added complexity and length to the process of converting a topworks from fail closed to fail open, and this reversal restores that O-ring so the conversion process returns to its original steps.

Effective 9/1/2026, High Pressure Control Valve Topworks again include both O-rings, as they did prior to the June 18 notice. No action is needed on your part.

Associated repair kits will continue to have one less O-ring as communicated in the June 18th notice.

The serial number range for products built without the O-ring on the atmospheric side is 2261590035 – 2262450271.



Brian Levings, Director of Product Management | blevings@kimray.com | 52 NW 42nd St. Okla. City, OK 73118