

## RUV, RUMB, AND RUWD REPAIR KITS

### Missing Part in Repair Kits

This product notice is to inform you that some RUV, RUMB, and RUWD outgoing repair kits are missing an o-ring, part 329HSN.

On 6/1/18, an error was made in the Bill of Material maintenance on repair kits RUV, RUMB, and RUWD, which resulted in the missing o-ring. The error was detected and fixed on 11/27/18.

Here are the next steps you should take:

- Check your stock of RUV, RUMB, and RUWD repair kits for a stamped manufacture date between 6/1/2018 and 11/27/2018. A date within this range indicates that the repair kit will be missing the o-ring.
- Contact your customers who may have affected repair kits to find out if they are missing the o-ring.
- Contact Jenny Kenendy on our Customer Service team (405-525-4298), or your local Kimray store to report how many o-rings you need for replacements, and they will send those to you.

Need Quick Tip and  
Repair Videos?



Search for **Kimray Inc.**  
on Youtube