

RAY PILOT PLUG SEATS / GLYCOL ELASTOMERS



CHANGE TO THE PILOT PLUG SEATS

We have made a slight design change to the A, H, and Y pilot plug seats. There is now a lip rather than a recess on the seat. This will make it easier to install. Make sure your repair shops are aware.

The effective date for this change is 2/06/2018.

GLYCOL ELASTOMERS

We are moving to HSN for our standard elastomer in the Kimray Glycol Pump. The new code will be GAJ-HSN.

The effective date for this change is 03/01/18.