

## DISCONTINUING ALL GEN II LIQUID LEVEL CONTROLLERS WITH FLANGED AND HAMMER UNION CONNECTIONS

This product notice is to inform you that we have discontinued all Gen II codes with flanged and hammer union connections.

New base codes for Gen 3 flanged and hammer union connections are listed below:

Flanged	Gen 3 Code
2" 150RF LH	LCA
2" 150RF RH	LCJ
2" 600RF LH	LCC
2" 600RF RH	LCM
3" 300RF LH	LCV
3" 600RF LH	LCW
3" 600RF RH	LDF
4" 150RF LH	LDM
4" 150RF RH	LDV
4" 300RF LH	LDN
4" 300RF RH	LDW

Hammer Union	Gen 3 Code
3" HU LH	LDC
3" HU RH	LDL
5" HU LH	LEM
5" HU RH	LEV

As always, if an additional code is needed, you can request the code via the "New End Item request" form.

If there are any codes you are not able to order, don't hesitate to contact me to get it worked out.

Note: the only remaining active Gen II codes are those with "S6B" option, 316 stainless steel body. This rare option will not be available in Gen 3 for several months.

